

<b>Canoe Repairs</b>			
<b>Part</b>	<b>Part Cost</b>	<b>Estimated Labor</b>	<b>Total</b>
<b>Kevlar Skid Plates</b>	\$100	\$50-\$100	\$150-\$200
<b>Fiberglass Skid Plates</b>	\$25	\$50-\$100	\$75-\$125
* Skid plate kits must be purchased from CanoeSport Outfitters in order for us to install them. If you supply the skid plate kit we charge \$90 for installation. In addition, since we cannot verify the resin mix, its' age or quality we will not guarantee it will stick.			
* Skid plate pricing includes installation at both the bow and the stern			
<b>Web or Cane Seat Installation</b>	\$55	\$25-\$50	\$80-\$105
<b>Plastic Bucket Seat</b>	\$45	\$25-\$50	\$70-\$95
<b>Thwart Installation, Wood</b>	\$40	\$25-\$50	\$65-\$90
<b>Thwart Installation, Aluminum</b>	\$35	\$25-\$50	\$65-\$85
<b>Ash Yoke Installation</b>	\$55	\$25-\$50	\$80-\$105
* Seats, thwarts, and yoke repairs involve replacing that item only. Additional costs will apply if we need to install hanging brackets or replace hardware.			
<b>Aluminum Gunwales</b>	\$150	\$100-\$200	\$250-\$350
* Gunwale replacement is for standard silver aluminum gunwales shipped on the manufacturers truck. Additional charges apply for black aluminum gunwales or if they need to ship common carrier.			
<b>Royalex/Plastic Gouge Repair</b>	\$10	\$25-\$50	\$35-\$60
<b>Royalex Cold Crack Repair</b>	\$60	\$50-\$100	\$110-\$160
* Cost to repair cold cracks is based on a single medium or small crack running no more than 12" down the side of the canoe. Additional cracks or cracks that continue all the way into the hull will incur additional costs.			
<b>Kayak Repairs</b>			
<b>Part</b>	<b>Part Cost</b>	<b>Estimated Labor</b>	<b>Total</b>
<b>Fiberglass Skid Plates</b>	\$25	\$50-\$100	\$75-\$125
<b>Fiberglass Keel Strip</b>	\$50	\$50-\$150	\$100-\$200
* Skid plate kits and keel strip must be purchased from CanoeSport Outfitters in order for us to install them. If you supply the skid plate/keel strip we charge \$90 for installation. In addition, since we cannot verify the resin mix, its age, or quality we will not guarrantee it will stick.			
* Skid plate pricing includes installation at both the bow and the stern			
<b>Rudder Installation</b>	\$200-\$250	\$25-\$50	\$225-\$300
<b>Rudder Cable Replacement</b>	\$30-\$50	\$25	\$55-\$75
<b>Foot Braces</b>	\$50-\$75	\$25-\$50	\$75-\$125
<b>Skeg Repair</b>	\$40-\$60	\$25	\$65-\$85
<b>Compass Installation</b>	\$100-\$200	\$25-\$50	\$125-\$250
<b>Bulkhead Repair, Sealant</b>	\$10	\$25	\$35
<b>Bulkhead Repair, Fiberglass</b>	\$25-\$50	\$50-\$100	\$75-\$150
<b>Fishing Accessories</b>	MSRP	\$10	MSRP + \$10
* Fishing accessories not purchased from CanoeSport Outfitters will be installed for \$20 each			
<b>Plastic Welding Cracks</b>	<i>Price given after inspection only</i>		

<b>Stand Up Board Repairs</b>			
<b>Part</b>	<b>Part Cost</b>	<b>Estimated Labor</b>	<b>Total</b>
<b>Inflatable Patch</b>	\$20-\$40	\$50-\$100	\$60-\$140
<b>Deck Cleats/Leash Plug Installation</b>	\$20-\$40	\$50-\$100	\$70-\$140
<b>Nose Guard/Skid Plate</b>	MSRP +\$20	\$50-\$100	MSRP + \$70-\$120
<b>General Repairs</b>			
<b>Part</b>	<b>Part Cost</b>	<b>Estimated Labor</b>	<b>Total</b>
<b>Gel Coat Repair</b>	\$30-\$50	\$50-\$100	\$80-\$150
<b>Fiberglass Patching</b>	\$15-\$30	\$25-\$50	\$40-\$80
* Gel coat and fiberglass repair costs are based on repairs about the size of a hand. Larger repairs or badly damaged boats will need to be inspected to provide an accurate repair cost.			
<b>Black Bungee Replacement</b>	\$1.25/foot	\$25	\$25+
<b>Colored Bungee Replacement</b>	\$2.25/foot	\$25	\$25+
* We stock a variety of colored deck bungee including purple, lime, orange, and blue!			
<b>Deck Lines</b>	\$2.25/foot	\$25	\$25+
<b>Deck Cleats</b>	\$2	\$25	\$25+